




(Pull the center slide all the way out until it reaches the end)




You will see a locking clip at the end point of the center slide. Push it down and unlock the center slide.





Now put the center slide right next to the rackmount chassis. You should be able to find screw holdes on both sides of chassis. Holes are used for mounting the center slide. Later, the center slide will be use for attaching the sliding rail.






Aline front outter rail to the indent of L bracket between Point A & B.





Repeat previous steps to secure sliding rails on both sides.



Reattach inner rail back to center rail